



Sun Devil Auto #1225
8660 E FRANK LLOYD WRIGHT BLVD
SCOTTSDALE, AZ 85260
(480)922-6300

PAGE 1

Customer ID: [REDACTED]
Name: TOBY DION
Address: [REDACTED]
Address 2: [REDACTED]
City, State, Zip Code: TEMPE, AZ, 85284
Home Phone: [REDACTED]
Work Phone: () - [REDACTED]
Mobile Phone: [REDACTED]
Tax Exempt #: [REDACTED]

Year: 16
Make: NISSAN
Model: TITAN XD
Lic No: KS6912
VIN: 1N6BA1F29GN502522
Color: RED
Engine: 5.0L V8 F DO
Mileage In: 161000
Mileage Out: 161000

Create Date: 06/30/26 12:35:43
Date/Time: 07/23/26 15:57:40
Workorder #: 49437
Invoice #:
Email Address: [REDACTED]
PO Number:
Fleet/Wholesale: N

Salesperson: J. DEWEY

Service comments:

COMPLAINT: IDLER PULLEY FAILURE, SERPENTINE FELL OFF - VEHICLE TOWED TO SHOP
CAUSE: IDLER PULLEY BEARING FAILED, SERPENTINE BELT DAMAGED
CORRECTION: REPLACE SERPENTINE BELT & IDLER PULLEY

COMPLAINT: DRIVER STATED ADDITIONALLY THAT VEHICLE IS STILL SEVERELY HESITATING TO ACCELERATE, FEELS LIKE TURBOS ARE NOT
SPOOLING UP TO ASSIST VEHICLE ACCELERATION. RECHECK PREVIOUS WORK DONE AS THERE ARE NO LONGER LIGHTS ON DASH AFTER
REPAIRS.
CAUSE: REPLACED AND RE CALIBRATED WASTE GATE ACTUATOR FOR TURBO TO ELIMINATE FAULTY PARTS POSSIBILITY. DETERMINED
VEHICLE STILL HESITATES TO ACCELERATE DUE TO INTERNAL TURBO FAILURE.
CORRECTION: REPLACE TURBOCHARGERS WITH NISSAN REPLACEMENT KIT. 1-2 DAYS OUT FROM LOS ANGELES.

TIRE PRESSURE: LF __ RF __ LR __ RR __ SPARE __

TREAD DEPTH: LF __/32 RF __/32 LR __/32 RR __/32 SPARE __/32

BRAKE PAD THICKNESS: LF __ RF __ LR __ RR __

REVISED ESTIMATE AUTHORIZATION(S):

AUTH. BY: CONTACT: TOBY DION ADD. AMT: 6873.88
DATE: 07-23-26 TIME: 3:57 PM PREVIOUS EST: 0.00 REV EST: 6873.88

Work Authorized:

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
1	DVI			DIGITAL VEHICLE INSPECTION	0.00	0.00	0.00
1	*tow			TOWING	0.00	0.00	0.00
1	*11925EZ40B			PULLEY ASSY-IDLER	141.99	0.00	141.99
1	LENG			LABOR - ENGINE	0.00	61.50	61.50
1	*4061155			ACCESSORY DRIVE SERPENTINE BEL	163.99	0.00	163.99
Sub-total:					305.98	61.50	367.48
1	*14480EZ40C			WASTE GATE ACTUATOR	0.00	0.00	0.00
1	*LST			LOW SIDE TURBO	1,587.63	0.00	1,587.63
1	*HST			HIGH SIDE TURBO	3,749.80	0.00	3,749.80
1	LENG			LABOR - ENGINE	0.00	1,435.00	1,435.00
1	MILITARY			50% OFF LABOR	0.00	(717.50)	(717.50)
Sub-total:					5,337.43	717.50	6,054.93

SEE NEXT PAGE



Sun Devil Auto #1225
8660 E FRANK LLOYD WRIGHT BLVD
SCOTTSDALE, AZ 85260
(480)922-6300

PAGE 3

Customer ID: [REDACTED]
Name: TOBY DION
Address: [REDACTED]
Address 2: [REDACTED]
City, State, Zip Code: TEMPE, AZ, 85284
Home Phone: [REDACTED]
Work Phone: () - [REDACTED]
Mobile Phone: [REDACTED]
Tax Exempt #: [REDACTED]

Year: 16
Make: NISSAN
Model: TITAN XD
Lic No: KS6912
VIN: 1N6BA1F29GN502522
Color: RED
Engine: 5.0L V8 F DO
Mileage In: 161000
Mileage Out: 161000

Create Date: 06/30/26 12:35:43
Date/Time: 07/23/26 15:57:40
Workorder #: 49437
Invoice #:
Email Address: [REDACTED]
PO Number:
Fleet/Wholesale: N

Salesperson: J. DEWEY

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
------	--------	-----	-----	-------------	-------	-------	-------

*** Customer Wishes To Discard Old Parts ***

These Parts And/Or Services Were Declined by the Customer:

1	*144D1EZ49CRE	reman turbo oem
1	LENG	LABOR - ENGINE

Turbocharger Assembly R&R (N/A)

Includes: The removal of component and all necessary components for access. Does not include: System diagnosis, testing, or a vehicle road test.

1	AAA10	F&F LABOR DISCOUNT
---	-------	--------------------

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Title to the merchandise as purchased as evidenced by invoice is retained by the seller until entire price of same has been paid. Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft, or any other cause beyond our control. ***WORKORDER ONLY, NOT AN INVOICE***

Customer Signature

X _____

TECH: 009F2V YASSER

PARTS TOTAL	5,643.41
SALES TAX	451.47
LABOR TOTAL	779.00
GRAND TOTAL	6,873.88

THIS IS A WORKORDER, NOT AN INVOICE! DO NOT MAKE ANY PAYMENTS FROM THIS PAPERWORK!

QUALITY ASSURANCE			
Must be filled out for every vehicle. Put N/A if not applicable.			
	Specification	Performed By	Verified By
Wheel Torque			
Oil Capacity			
Oil Weight/Type			
Drain Plug Torque			