

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN			
Fixed or replaced		Passed	
1	Correct VIN plate and anti-theft labels		
2	Clean Experian Auto Check Confirm		
3	No reported accidents/flood damage/salvage		

UNDER THE HOOD			
Fixed or replaced		Passed	
4	Battery (condition, fluid level, load test)		
5	Alternator (belt condition/tension, charging)		
6	Water pump (noise/leaks)		
7	Ignition system operation		
8	Fuel system operation (connections/leakage)		
9	Fuel filter (replace per maintenance schedule)		
10	Radiator (leaks, road hazard damage)		

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN			
Fixed or replaced		Passed	
1	Correct VIN plate and anti-theft labels		
2	Clean Experian Auto Check Confirm		
3	No reported accidents/flood damage/salvage		

UNDER THE HOOD			
Fixed or replaced		Passed	
4	Battery (condition, fluid level, load test)		
5	Alternator (belt condition/tension, charging)		
6	Water pump (noise/leaks)		
7	Ignition system operation		
8	Fuel system operation (connections/leakage)		
9	Fuel filter (replace per maintenance schedule)		
10	Radiator (leaks, road hazard damage)		

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN			
Fixed or replaced		Passed	
1	Correct VIN plate and anti-theft labels		
2	Clean Experian Auto Check Confirm		
3	No reported accidents/flood damage/salvage		

UNDER THE HOOD			
Fixed or replaced		Passed	
4	Battery (condition, fluid level, load test)		
5	Alternator (belt condition/tension, charging)		
6	Water pump (noise/leaks)		
7	Ignition system operation		
8	Fuel system operation (connections/leakage)		
9	Fuel filter (replace per maintenance schedule)		
10	Radiator (leaks, road hazard damage)		

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN		
Fixed or replaced		Passed
1	Correct VIN plate and anti-theft labels	
		✓
2	Clean Experian Auto Check Confirm	
3	No reported accidents/flood damage/salvage	

UNDER THE HOOD		
Fixed or replaced		Passed
4	Battery (condition, fluid level, load test)	
		✓
5	Alternator (belt condition/tension, charging)	
		✓
6	Water pump (noise/leaks)	
		✓
7	Ignition system operation	
		✓
8	Fuel system operation (connections/leakage)	
		✓
9	Fuel filter (replace per maintenance schedule)	
		✓
10	Radiator (leaks, road hazard damage)	

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN		
Fixed or replaced		Passed
1	Correct VIN plate and anti-theft labels	
		✓
2	Clean Experian Auto Check Confirm	
3	No reported accidents/flood damage/salvage	

UNDER THE HOOD		
Fixed or replaced		Passed
4	Battery (condition, fluid level, load test)	
		✓
5	Alternator (belt condition/tension, charging)	
		✓
6	Water pump (noise/leaks)	
		✓
7	Ignition system operation	
		✓
8	Fuel system operation (connections/leakage)	
		✓
9	Fuel filter (replace per maintenance schedule)	
		✓
10	Radiator (leaks, road hazard damage)	

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN		
Fixed or replaced		Passed
1	Correct VIN plate and anti-theft labels	
		✓
2	Clean Experian Auto Check Confirm	
3	No reported accidents/flood damage/salvage	

UNDER THE HOOD		
Fixed or replaced		Passed
4	Battery (condition, fluid level, load test)	
		✓
5	Alternator (belt condition/tension, charging)	
		✓
6	Water pump (noise/leaks)	
		✓
7	Ignition system operation	
		✓
8	Fuel system operation (connections/leakage)	
		✓
9	Fuel filter (replace per maintenance schedule)	
		✓
10	Radiator (leaks, road hazard damage)	

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN			
Fixed or replaced		Passed	
1	Correct VIN plate and anti-theft labels		
2	Clean Experian Auto Check Confirm		
3	No reported accidents/flood damage/salvage		

UNDER THE HOOD			
Fixed or replaced		Passed	
4	Battery (condition, fluid level, load test)		
5	Alternator (belt condition/tension, charging)		
6	Water pump (noise/leaks)		
7	Ignition system operation		
8	Fuel system operation (connections/leakage)		
9	Fuel filter (replace per maintenance schedule)		
10	Radiator (leaks, road hazard damage)		

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN			
Fixed or replaced		Passed	
1	Correct VIN plate and anti-theft labels		
2	Clean Experian Auto Check Confirm		
3	No reported accidents/flood damage/salvage		

UNDER THE HOOD			
Fixed or replaced		Passed	
4	Battery (condition, fluid level, load test)		
5	Alternator (belt condition/tension, charging)		
6	Water pump (noise/leaks)		
7	Ignition system operation		
8	Fuel system operation (connections/leakage)		
9	Fuel filter (replace per maintenance schedule)		
10	Radiator (leaks, road hazard damage)		

VIN 1N6BA1F29GN502522
Stock # 2003105513
Inspected On 08/14/2024

FROM THE VIN		
Fixed or replaced		Passed
1	Correct VIN plate and anti-theft labels	
		✓
2	Clean Experian Auto Check Confirm	
3	No reported accidents/flood damage/salvage	

UNDER THE HOOD		
Fixed or replaced		Passed
4	Battery (condition, fluid level, load test)	
		✓
5	Alternator (belt condition/tension, charging)	
		✓
6	Water pump (noise/leaks)	
		✓
7	Ignition system operation	
		✓
8	Fuel system operation (connections/leakage)	
		✓
9	Fuel filter (replace per maintenance schedule)	
		✓
[REDACTED]		
[REDACTED]ks, road hazard damage)		

VIN 1N6BA1F29GN502522

Stock # 2003105513

Inspected On 08/14/2024

FROM THE VIN		
Fixed or replaced		Passed
1	Correct VIN plate and anti-theft labels	
		✓
2	Clean Experian Auto Check Confirm	
3	No reported accidents/flood damage/salvage	

UNDER THE HOOD		
Fixed or replaced		Passed
4	Battery (condition, fluid level, load test)	
		✓
5	Alternator (belt condition/tension, charging)	
		✓
6	Water pump (noise/leaks)	
		✓
7	Ignition system operation	
		✓
8	Fuel system operation (connections/leakage)	
		✓
9	Fuel filter (replace per maintenance schedule)	
		✓
10	Radiator (leaks, road hazard damage)	